

Brownsville Independent School District

Brownsville Learning Academy





Description of Non-Compliance

- Toilet lever on wrong side

Picture Location:
Men's Visitors Restroom



Date Corrected: **Dec 5, 2013**

Name of Reviewer: **F Villarreal**



Description of Non-Compliance

- Missing insulation on sink drain

Picture Location:
Women's Visitors Restroom



Date Corrected: **Dec 5, 2013**

Name of Reviewer: **F Villarreal**



Description of Non-Compliance

- Missing insulation on sink drain

*Portables Removed
from Campus*

Picture Location:
Building 503 - Boy's Restroom

Date Corrected: **Sep 2, 2013**

Name of Reviewer: **F Villarreal**



Description of Non-Compliance

- Missing grab bars

*Portables Removed
from Campus*

Picture Location:
Building 503 - Boy's Restroom

Date Corrected: **Sep 2, 2013**

Name of Reviewer: **F Villarreal**



Description of Non-Compliance

- Missing signage

*Portables Removed
from Campus*

Picture Location:
Building 503 - Boy's & Girl's Restrooms

Date Corrected: **Sep 2, 2013**

Name of Reviewer: **F Villarreal**



Description of Non-Compliance

- Missing grab bars
- Toilet lever on wrong side

*Portables Removed
from Campus*

Picture Location:
Building 503 - Girl's Restroom

Date Corrected: **Sep 2, 2013**

Name of Reviewer: **F Villarreal**



Description of Non-Compliance

- Missing insulation on sink drain



Picture Location:
Nurse's Restroom

Date Corrected: **Dec 5, 2013**

Name of Reviewer: **F Villarreal**