

Brownsville Independent School District

Sam's Stadium



Description of Non-Compliance

- Missing insulation on sink drain

Picture Location:
Home Side - Men's Restroom



Date Corrected: **Sep 4, 2013**

Name of Reviewer: **F Villarreal**



Description of Non-Compliance

- Missing insulation on sink drain

Picture Location:
Visitor's Side - Men's Restroom



Date Corrected: **Sep 4, 2013**

Name of Reviewer: **F Villarreal**